READ & ROUTE

Dealer _____   Service Technician _____   Parts Department _____

Service Mgr. _____   Service Technician _____   Sales Department _____

TOPIC:

Lack of Fuel Delivery to Engine

MODELS & SERIAL NUMBERS AFFECTED:

Models:	Serial Numbers:
HydroCut Series	1429 - 2058
1000Z Series	2251 - 3008
IS1000Z Series	1981 - 2647
IS1500Z Series	101 - 2268
IS3000Z Series	2681 - 5387
IS4500ZBL3561	101 - 475

SUBJECT:

Engine runs rough, stalls or will not start due to lack of fuel to the carburetor. The potential exists for improper fuel draw from the tank due to the loss of clamp on the tank fitting and internal hose, allowing the hose to come loose and draw air, or fall off of the fitting.

CORRECTIVE PROCEDURES:

1. Remove the fuel hose from the tank.

2. Remove the fitting and grommet from the fuel tank. If the clamp is not retaining the internal hose to the fitting or the internal hose is not attached to the fitting, the hose assembly needs to be replaced. See chart on Page 2 for hose assembly part numbers and models affected.

3. Install the hose (screen end first) into the tank. Lubricate the grommet with petroleum jelly (i.e. Vaseline™) and slowly press the grommet into the tank (see Figure 1).

4. Lubricate the hose, clamp and fitting with petroleum jelly and slowly insert the fitting into the grommet (see Figure 2).

5. Reconnect the fuel hose to the fitting and secure with the hose clamp.

Apply Lubricant Here

**Figure 1.   Lubricate & Install Grommet**

Apply Lubricant Here

Figure 2.   Lubricate & Install FItting & Hose

Part No.	Description	Fits Models
5300046	Fuel Hose Assembly, 20"	HydroCut Series 1000Z Series IS1000Z Series IS1500Z Series IS3000Z Series
5300047	Fuel Hose Assembly, 26"	IS4500ZBL3561

WARRANTY INFORMATION:

Failure Type: **Failure Code:**

Cause of Failure:

Work Performed: Repaired per Service Bulletin F078

Repair Parts:

	Qty.	Part No.	Description
	1	5300046	Fuel Hose Assembly, 20"
OR	1	5300047	Fuel Hose Assembly, 26"

Eligible for Pickup and Delivery Reimbursement If Performed: No   **Total Hours:**   0.2