

April 1997

TOPIC: POSSIBLE PREMATURE BELT FAILURE

MODELS

AFFECTED: PCZ RIDERS
Serial no. 101-300

Ferris Industries has determined a number of machines were assembled with the pump drive pulleys in the improper location, which could cause a premature belt failure. To rectify this, a Pump Pulley Locating Kit (45124) is available through the Parts Department.

The modifications described in this service bulletin will be incorporated into production mowers beginning with the serial number after the ones listed above. It is important to note that this is a mandatory fix. It is not necessary to wait for a failure to install the kit.

\$40 labor will be paid.

