F022

April 1997

Service Bulletin

TOPIC: ENGINE INTERRUPTION DURING OPERATION

MODELS AFFECTED: PROCUT Z - serial no. 101 - 300

Field reports have indicated that the parking brake handle bounces during operation causing an engine interruption problem.

To rectify this, a Brake Spring Kit (45129) is available through the Parts Department. This kit includes all necessary components, hardware and installation instructions.

Please note, this is a mandatory fix.

\$20 labor will be paid.



