

May 2001

TOPIC: INCORRECTLY ASSEMBLED SEAT STOP ROD

MODELS

AFFECTED: **1000ZKAV21/48** - serial no. 441-620
1000ZKAV23/52 - serial no. 341-430
IS3000ZKAV25/61 - serial no. 706-905

Ferris Industries has determined that the above listed models may have the seat stop rod assembled incorrectly, which may cause the rod to bind. To rectify this problem, the seat rod will need to be removed and reinstalled in the orientation shown in the illustration below.

