

June 2001

TOPIC: FAN SHIELD INTERFERENCE

MODELS

AFFECTED: **1000ZKAV21/48** - serial no. 101-440
1000ZKAV23/52 - serial no. 101-340

Ferris Industries has determined that the fan shields may have to ability to come in contact with the fan mount shafts on top of the hydraulic pumps. To rectify this, a new 1000Z fan shield kit (46803) is available through the Parts Department on a per-customer basis.

The modifications described in this kit will be incorporated into production mowers beginning with the serial numbers after the ones listed above. It is important to note that this kit should only be installed if a customer reports an interference issue. Do not assume that this kit will automatically be required on existing mowers. We have found that the current fan shield configuration performs well in most conditions, and that generally speaking the modification kit is not required. However, if a customer is having problems with the shields contacting the pump shafts, the kit will correct this problem.

\$15 labor will be paid.

