

March 2003

TOPIC: ENGINE STARTING PROBLEMS

MODELS

AFFECTED: IS4000Z/KAV27 - ALL
IS4000Z/D31 - ALL
IS5000Z/C31D - S/N: 101-410

Ferris Industries has identified an intermittent problem evidenced by a failure of the starter solenoid to engage on the above listed models.

To rectify this problem, Ferris has developed a Starter Solenoid Relay Kit (see chart below) that is added to the electrical control circuit that starts the engine.

These kits are available through the Parts Department.

Model	Kit Part No.
IS4000Z/KAV27	48583
IS4000Z/D31	48586
IS5000Z/C31D	48589

Please note, this is a **MANDATORY FIX** that must be installed on all models and serial numbers listed above.

One-half (1/2) hour labor will be paid.

