

May 2003

TOPIC: FUEL HOSES ROUTED INCORRECTLY

MODELS

AFFECTED: IS5000Z/C31D - S/N: 566-635

Ferris Industries has determined that the fuel hoses connected to the water separator may be installed incorrectly.

Verify the hose routing by referring to the illustration below. If the hose routing is incorrect, disconnect and reconnect the hoses in the proper locations shown.

Follow the "Priming The Fuel System" instructions in either the setup instructions or operator's manual.

One-tenth (1/10) hour labor will be paid.

