



**READ & ROUTE**

Dealer \_\_\_\_\_ Service Technician \_\_\_\_\_ Parts Department \_\_\_\_\_

Service Mgr. \_\_\_\_\_ Service Technician \_\_\_\_\_ Sales Department \_\_\_\_\_

**TOPIC:**

Possible Oil Reservoir Cap Leak

**MODELS & SERIAL NUMBERS AFFECTED:**

**Models:**

All IS1500Z Models

**Serial Numbers:**

101-948


**SUBJECT:**

Early production IS1500Z Series zero-turn riders were built with oil reservoir caps that may leak. New caps (part number 5100017) are available, and will be shipped to you automatically, **at no charge**.

**CORRECTIVE PROCEDURES:**

Please replace the caps on all units in your inventory and all retailed units that fall within the serial number range.

Only units in the listed serial number range are affected by this update due to an interference between the reservoir and the original cap. Product above the serial number range has had the interference corrected.



**Figure 1. Oil Reservoir**

**A. Reservoir Cap**

**B. Reservoir**

**WARRANTY INFORMATION:**

**Failure Type:**

**Failure Code:**

**Cause of Failure:**

**Work Performed:** Repaired per Service Bulletin F075

Repair Parts:	Qty.	Part No.	Description
	1	5100017	CAP, Hydraulic

**Eligible for Pickup and Delivery Reimbursement If Performed:**

No

**Total Hours:**

0