



READ & ROUTE

Dealer _____ Service Technician _____ Parts Department _____
Service Mgr. _____ Service Technician _____ Sales Department _____

TOPIC:

IS1500Z Bolt in Front End Repair Kit

MODELS & SERIAL NUMBERS AFFECTED:

Models:

IS1500Z units without Factory Supplied Roll
Bar (ROPS)

Serial Numbers:

2000612053 and
Below

SUBJECT:

Reports from the field are showing a small number of failures of the IS1500Z front frame. Only units in severe duty applications (such as extreme amounts of curb jumping) seem to be affected. A kit is now available for repair on a fix as fail basis.

CORRECTIVE PROCEDURES:

1. Order and install Front End Repair Kit (Part No. 5600078)

WARRANTY INFORMATION:

Failure Type: F40 Failure Code: BC

Work Performed: Repaired per Service Bulletin F084

Repair Parts:	Qty.	Part No.	Description
	1	5600078	Front End Repair Kit

Eligible for Pickup and Delivery Reimbursement If Performed:	No	Total Hours:	3
--	----	--------------	---

REVISED/UPDATED COPY

a subsidiary of SIMPLICITY MANUFACTURING, INC.