



F096
SERVICE BULLETIN

NOVEMBER 07

POTENTIAL FOR THE BATTERY CABLE INSULATION FAILURE ON PROCUT S SERIES MODELS

MODELS AFFECTED			
Brands	Model Nos.:	Serial No. Range:	Description:
Ferris	5900631, 5900651, 5900652, 5900701	2012588981 & Below	ProCut S Series Three Wheeled Riding Mowers

DETAIL


Field reports indicate that models listed above serial range could potentially have issues with the battery cable insulation failing.

INSPECTION PROCEDURES

1. Refer to Figure 1. If your machine is equipped with vinyl hose clamp (A), no further action is require. If not equipped with the hose clamp or if equipped with wire tie continue to corrective procedures.

CORRECTIVE PROCEDURES

1. Order and install kit number 5600168.



**Figure 1. Inspect for Vinyl Hose Clamp
A. Vinyl Hose Clamp**

WARRANTY INFORMATION

Fill in the Warranty Claim Form with the following information.

Failure Location Category:	Electrical
Failure Location Code:	C77
Defect Code / Failure Mode	AW
Control / Evaluation No.:	F096
Pickup & Delivery:	N/A
Total Hours:	0.3

Cause of Failure:	N/A
Work Performed:	F096
Repair Parts:	5600168

