

SERVICE**BULLETIN****SB #:** F104**BRANDS:****DATE:** AUGUST 2010**TO:** ALL AUTHORIZED FERRIS DEALERS**SUBJECT:** CLUTCH SPACING - A DIFFERENCE IN CRANK SHAFT LENGTHS BETWEEN 25HP & 26HP KAWASAKI ENGINES HAS CAUSED AN ISSUE WITH THE PROPER CLUTCH CLAMPING.**MODELS:** SEE LIST BELOW

Brand	Model Number	Serial Number Range	Description
Ferris	5900933	2014278067 - 2014545411	Procut S Series Three-Wheeled Riding Mower

DESCRIPTION

This bulletin details a correction procedure to make sure that the clutch is properly spaced.

CORRECTIVE PROCEDURES

1. Order and install Kit #5600458.

WARRANTY:

File for warranty reimbursement using e-Claim at www.ThePowerPortal.com. Use the values listed below when filling out the claim. The information in the "Brand" block indicates which tab the claim should be filed under. *Note: File only one unit per claim form.*

Brand	Ferris		
Failure Location Category	Lawn & Garden Engine	Cause of Failure	F104
Failure Location Code	F73	Work Performed	F104
Defect Code/Failure Mode	AW	Repair Parts Used	5600458
Control/Evaluation Number	F104		
Pick-Up & Delivery	N/A		
Total Hours (Tenths)	Repair: 0.5		