



**F089**  
 SERVICE BULLETIN  
 JANUARY 07

**INCORRECT WIRING ON IS2000Z EXPORT MODELS**

| MODELS AFFECTED |   |                    | EXPORT MODELS ONLY   |
|-----------------|---|--------------------|--|
| Brands          | Model Nos.:                                 | Serial No. Range:  | Description:   |
| Ferris          | 5900627,<br>5900628,<br>5901191,<br>5901192 | 2000669521 & Below | IS2000Z, 20 HP Export Zero-Turn Riding Mower w/ Mower Deck |
| Simplicity      | 5901187,<br>5901188,<br>5901189,<br>5901190 | 2000669521 & Below | IS2000Z, 20 HP Export Zero-Turn Riding Mower w/ Mower Deck |

**DETAIL**

Quality audits indicate that models listed in the serial number range listed above may have incorrect wiring.

**CORRECTIVE PROCEDURES**

1. Order and install kit number 5600095.
2. After installing kit number #5600095 and checking and correcting the wiring, if the machine fails the test detailed in Step 12 of the installation instruction for kit number 5600095, a new one (1) second timer (5100609) and a fuel PULL solenoid relay (5100980) will need to be ordered and installed.

**WARRANTY INFORMATION**

Fill in the Warranty Claim Form with the following information.

|                           |      |
|---------------------------|------|
| Failure Type:             | C77  |
| Failure Code:             | EF   |
| Control / Evaluation No.: | F089 |
| Pickup & Delivery:        | N/A  |
| Total Hours:              | 1.0  |

|                   |   |
|-------------------|---|
| Cause of Failure: | Manufacturing Defect  |
| Work Performed:   | F089  |
| Repair Parts:     | 5600095;<br>5100609 (If necessary, see Step #2),<br>5100980 (If necessary, see Step #2) |

