

SERVICE**BULLETIN****SB #:** F106**BRANDS:****DATE:** OCTOBER 2010**TO:** ALL AUTHORIZED FERRIS DEALERS**SUBJECT:** UPDATES TO EVOLUTION ZERO-TURN RIDING MOWERS W/ 36" MOWER DECK**MODELS:** SEE LIST BELOW

Brand	Model Number	Serial Number Range	Description
Ferris	5900778	See chart below.	Evolution Series Zero-Turn Riding Mower w/ 36" Mower Deck

DESCRIPTION

This bulletin collects several updates that have been made available for the Evolution product in a comprehensive list to help ensure that all applicable changes have been completed on affected machines.

CORRECTIVE PROCEDURES

- Using the chart below verify that your machines have been updated to reflect all of the changes listed below.

Work Required / Kit No.:	Description:	Serial Number Range:	Notes / Purpose
Service Bulletin F102	Wheel motor bolt update	2013447320 - 2013704369	This bulletin details a corrective procedure to make sure that all wheel motor front cover bolts are properly seated and correctly torqued. This will ensure that the wheel motor will not be subject to leakage. Most of the affected units have already been reworked. Follow the Inspection Procedure to make sure change has been already done.
Product Information Notice # 45	Incorrect positioning of stationary idler pulley	2013796826 & Below	This product information notice details an inspection and correction procedure to make sure that the stationary idler pulley has been installed in the correct position. The work detailed in this bulletin must be performed to prevent possible damage to the PTO drive belt.
5600380	Motion Control Cable Update	2013952387 & Below	This kit updates the motion control cables on the unit.
5404280B	Deck Lift Lever Update	2013497141 & Below	This kit updates the deck lift lever on the unit.
5600385	Knee Pad Retainer Kit	All	This kit updates the knee pads and the manner in which they are retained to the unit.

WARRANTY:

File for warranty reimbursement using e-Claim at www.ThePowerPortal.com. Use the values listed below when filling out the claim. The information in the "Brand" block indicates which tab the claim should be filed under. *Note: File only one unit per claim form.*

IMPORTANT NOTE: *If you file a warranty claim, the warranty claim should only contain the changes that you needed to perform to the specific unit. Please file accordingly for the Total Hours and Repair Parts Used by using the correct information from the chart below.*

Brand	Ferris	Cause of Failure	F106
Failure Location Category	L&G Body/Chassis	Work Performed	F106
Failure Location Code	H65	Repair Parts Used	
Defect Code/Failure Mode	DP	Service Bulletin F102:	See Service Bulletin F102
Control/Evaluation Number	F106	Product Information Notice # 45:	N/A
Pick-Up & Delivery	N/A	5600380:	5600380
Total Hours (Tenths):		5404280A:	5404280A
Service Bulletin F102:	See Service Bulletin F102	5600385:	5600385
Product Information Notice # 45:	0.3 hrs		
5600380:	2.0 hrs		
5404280A:	0.3 hrs		
5600385:	0.3 hrs		

BRIGGS & STRATTON POWER PRODUCTS GROUP, LLC
Distribution Sales & Customer Support