

June 1995

**TOPIC: FRONT CASTER BEARINGS**

**MODELS**

**AFFECTED: ALL FERRIS MOWERS**

Dear Dealer/Distributor:

There could be a potential problem with a limited number of front caster wheels on Ferris mowers. If a customer complains of not being able to get a grease gun on zerck fittings for caster wheel bearings, replace hub with part #1521181-3 and return old hub to Ferris with claim.

Please check dealer/distributor stock of part #1521181-3 to be sure that the replacement hubs will accept a grease gun. Return all defective hubs to Ferris as soon as possible to be replaced.

Sorry for any inconvenience that this problem may cause you or your customers.

Thank you in advance for your cooperation.

