

May 1997

TOPIC: IDLER PULLEYS CUTTING FUEL LINES

MODELS

AFFECTED: PROCUT Z - 52" MOWER DECK - serial no. 101-350

Field reports have indicated when the 52" mower deck is raised completely while the deck is in operation, the idler pulleys located on the mower deck cut the fuel lines.

To rectify this problem, a Fuel Line Relocation Kit (45142) is available through the Parts Department.

Please note, this is a mandatory fix. Do not wait for a failure to occur. Warranties will not be paid for machines that fail unless a claim is files for this bulletin.

\$20 labor will be paid.

