

October 1997

**TOPIC: ALUMINUM PUMP PULLEY FAILURE**

**MODELS**

**AFFECTED: PROCUT Z** - serial no. 101-500

Ferris Industries has determined that the aluminum pump drive pulleys do not provide a substantial life expectancy to match the other drive components.

To rectify this, a Pump Pulley Update Kit (45150) is available through the Parts Department.

The modifications described in this kit will be incorporated into production mowers beginning with the serial numbers after the ones listed above

\$40 labor will be paid.

