

January 2001

TOPIC: BATTERY RETAINER UPDATE

MODELS

AFFECTED: FERRIS IS3000ZKAV23/61

S/N 101-325

Field reports indicate that certain brands of lawn & garden batteries are experiencing interference with the battery retainer, preventing the battery from being properly secured. To rectify this, a new battery retainer (46552) is available through the Parts Department on a per-customer basis.

Modifications will be incorporated into production mowers beginning with the serial numbers after the ones listed above to allow for other batteries to be used. It is important to note that this part should only be installed if a customer is using any other battery besides a Deka brand battery.

In addition to the battery retainer (46552), a foam grip (25510) should be ordered to provide the same retaining features of the existing battery retainer.

