

November 2001

**TOPIC: CLUTCH DRIVE SPRING ANCHOR**

**MODELS**

**AFFECTED: IS4000Z/D31** - serial no. 376 - 435

Ferris Industries has determined the above listed serial number machines were shipped without the adjustable clutch drive spring anchor.

To rectify this, a Clutch Drive Spring Anchor Kit (47276) is available through the Parts Department.

The kit includes all the required components, hardware and instructions for installing the kit.

Please note, this is a mandatory fix.

One (1) hour labor will be paid per repair.

