F050

December 2001

Service Bulletin

TOPIC: CLUTCH DRIVE SPRING ANCHOR

MODELS AFFECTED: IS4000Z/KAV27 - serial no. 101 - 320

Field reports have indicated that obtaining the proper belt tension may be difficult to adjust and there have been reports of tension springs breaking. To rectify this, a Clutch Drive Spring Anchor Kit (47276) is available through the Parts Department on a per-customer basis.

The modifications described in this kit will be incorporated into production mowers beginning with the serial numbers after the ones listed above. It is important to note that this kit should only be installed if a customer reports difficulty adjusting the belt tension or repeated spring breaks. Do not assume that this kit will automatically be required on existing mowers.

One (1) hour labor will be paid per repair.



