



F094
SERVICE BULLETIN

SEPTEMBER 07

POTENTIAL FOR VENT LINE KINKING ON IS4500Z & IS5100Z DIESEL SERIES MOWERS

MODELS AFFECTED			
Brands	Model Nos.:	Serial No. Range:	Description:
Ferris	5900602	2012609622 - 2012609714	IS5100Z Series Zero-Turn Riding Mower w/ 33 HP Caterpillar Diesel Engine
	5901180, 5900626	2012613660 - 2012313995	IS4500Z Series Zero-Turn Riding Mower w/ 28 HP Caterpillar Diesel Engine

DETAIL

Field reports indicate that models listed in the serial number range above could potentially have issues with vent lines kinking

CORRECTIVE PROCEDURES

1. Order and install kit number 5600160.

WARRANTY INFORMATION

Fill in the Warranty Claim Form with the following information.

Failure Location Category:	Body/Chassis
Failure Location Code:	D63
Defect Code / Failure Mode	BW
Control / Evaluation No.:	F094
Pickup & Delivery:	N/A
Total Hours:	0.4

Cause of Failure:	N/A
Work Performed:	F094
Repair Parts:	5600160