



F097

SERVICE BULLETIN

MANDATORY UPDATE

APRIL 2008

Excessive Mower Deck Belt Tension on IS500ZBV2652 Series Zero-Turn Riding Mowers

MODELS AFFECTED			
Brands	Part Nos.:	Serial No. Range:	Description:
Ferris	5900704	2012678798 to 2012969257	IS500Z Series Zero-Turn Riding Mowers w/ 26HP Briggs & Stratton Engine & 52" Mower Deck

DETAIL

Quality audits indicate that units within the serial number range listed above could potentially have excessive tension exerted on the mower deck drive belt.

CORRECTIVE PROCEDURES

1. Order and install kit # 5600194.

WARRANTY INFORMATION

Fill in the Warranty Claim Form with the following information.

Failure Location Category:	Deck/Attachment
Defective Part ID Code:	F31
Defect Code	OA
Control Number:	F097
Pickup & Delivery:	N/A
Total Hours:	0.5

Cause of Failure:	N/A
Work Performed:	F097
Repair Parts:	5600194

WO 0XXXX

