

May 2002

TOPIC: DRIVE SHAFT THRUST BEARING UPGRADE

MODELS

AFFECTED: BGF32B - S/N 101-250
BGF32KA - S/N 101-245

Ferris Industries has added a thrust bearing to the gearbox output shafts to avoid the potential for wear between the Trans Axle Locking Collars and the Trans Axle bearing bulkheads.

A Thrust Bearing Upgrade Kit (47832) is available through the Parts Department and will be sent to all dealers/distributors with affected units.

NOTE: This is a mandatory fix.

Three-quarter (3/4) hour labor will be paid.

