

June 2002

TOPIC: PROPER BRUSH CUTTER CHAIN CURTAIN ASSEMBLY AND INSTALLATION

MODELS

**AFFECTED: BC25BE
BC25H**

Quality audits indicate that the Chain Curtain Bracket may be installed incorrectly which may allow contact between Cutting Blade and Chain Curtain.

When assembling units, verify that the Chain Curtain Bracket is installed with the cutout facing the rear of the machine and the chains are installed from the front of the bracket.

! DANGER

Improper assembly and/or installation of Brush Cutter Chain Curtain may contact between Cutting Blade and Chain Curtain and may result in severe injury or equipment damage.

